3 September 1963

REPLY TO

ATTN OF: P.E.

Monthly Activities Report for the Month of August 1963

TO: Commander WRSP-IV

> 1. Flight Discrepancies: There were no personal equipment discrepancies noted throughout the reporting period.

cook a five (5) day leave from 5 August to 9 Leaves: August 1963.

STATINTL

3. Personnel:

nnounced his desires to terminate his tour with the organization upon completion of the four (4) years minimum time. He desires to leave a month earlier (August 1964) if possible in order to establish his STATINT family before they start the 1964 school year.

- Seat Pack Maintenance: In addition to routine maintenance serviced five (5) ARDC and two (2) IAC seat packs.
- Equipment and Materiels
- a. Storage: The personal equipment storeroom in Hangar #3 was entered forcedly by persons unknown by tearing the hinges from the door. The incident was noticed on the 28th of August and reported immediately to the Security Office for further action. There is no apparent evidence of pilfering but an inventory of the personal equipment account will have to be accomplished for verification.
- Transfer Vehicle: A jeep ambulance from the Barstow salvage yard is expected sometime during the month of September 1963, for use as Approved For Release 2002/06/24: CIA-RDP75B00326R000200100020-1

STATINTL

STATINTL

Approved For Release 2002/06/24 : CIA-RDP75B00326R000200100020-1

a combination staging transfer vehicle and ambulance. The vehicle	
will be modified and furnished with air conditioning prior to being	STATINTL
utilized as a transfer vehicle.	STATINIL
c. Partial Pressure Suits: A reconditioned suit for	
was found on trial fittings to be too small. has been	STATINTL
plaguad with suit problems since his arrival in the organization. He	į
departed on 28 August for David Clark Company for on the spot fitting	}
and alterations to all three (3) suits issued to him. Additional suits	
for were received on 29 August and will be	
fitted to them as soon as their schedule permits.	STATINTL
has indicated a tentative proposal on the part of IAC to allow mixe.	,
cracks and crazing in certain areas of the Q336 faceplate in order to	
temporarily relieve the demand for this item in the field. This organ-	
idation has expressed disatisfaction with this proposal and does with	
concur with it's applicability to our operation.	STATINTL
and his partial pressure suits	ILLEGIB
on requisition. Headquarters has advised expiditious acti	
half of David Clark. The first suit is asseted in the a	
October. He is currently wearing the old number 3 suit	
and formerly the primary suit of	STATINTL
of Chippewa boot have been obtained for	STATINTL
d. Reasearch and Development: of Headquarters vis	Lt-
ed the organization with a new seat pack and specialized parachute with	
installed oxygen components. Presentation of the seat pack and para-	
2	

Approved For Release 2002/06/24 : CIA-RDP75B00326R000200100020-1

STATINTL

STATINTL

STATINTL

Approved For Release 2002/06/24 : CIA-RDP75B00326R000200100020-1

chute revealed they were not compatable with the requirements of this

VEB95

STATINTL

STATINTL

STA	TINTL
STAT	INITI

STATINTL

and reviewed the Q445 seat pack. Plans are under way to manufacture a prototype to our specifications. A tentative delivery date of the prototype could not be established at that time. The Q445 seat pack was favorably accepted by all attending the meeting with a few minor modifications to be made such as the height, tilt, seat quick

STATINTL

NCOIC Personal Equipment

disconnect. "beefed up" hardware, etc.

organization.